



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

| | | |
|--------|------------|---|
| 1 | OF | 3 |
| RFQ No | AM19653SI | |
| DATE | 11.05.2026 | |

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)
SAP No.6100016694

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

| | | | |
|--------------|------------|--------------|--|
| ON (Date) | 01.06.2026 | BY (Time) | |
|--------------|------------|--------------|--|

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: Complete Rehabilitation required for company owned vehicles CV-4783 and CU-2644 at Karachi Airport.

| S.No. | Description/Specifications | Location | Unit | Qty | Unit Price Rs. | Amount Rs. |
|-------|--|-------------------------------------|-----------|-----|-------------------|---------------|
| 1 | Engine Head Gasket New Engine head gasket OEM Recommended or equivalent | Karachi (Aviation) | EA | 2 | | |
| 2 | TURBO CHARGER TURBO CHARGER OEM Recommended or equivalent | Karachi (Aviation) | EA | 2 | | |
| 3 | Valves OEM Recommended or equivalent | Karachi (Aviation) | EA | 32 | | |
| 4 | Valve seals OEM Recommended or equivalent | Karachi (Aviation) | EA | 32 | | |
| 5 | Main Bearing MAIN <(>&<)> BIG END BEARING OEM Recommended or equivalent | Karachi (Aviation) | EA | 2 | | |
| 6 | Piston set PISTON SET OEM Recommended or equivalent | Karachi (Aviation) | EA | 8 | | |
| 7 | TIMING BELT OEM Recommended or equivalent | Karachi (Aviation) | EA | 2 | | |
| 8 | Piston ring set PISTON RING SET OEM Recommended or equivalent | Karachi (Aviation) | EA | 2 | | |
| 9 | Clutch Plate Clutch Plate OEM Recommended or equivalent | Karachi (Aviation) | EA | 2 | | |
| 10 | BRAKE New brake pads and brake shoe | Karachi (Aviation) | # | 2 | | |



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

| | | |
|--------|------------|---|
| 2 | OF | 3 |
| RFQ No | AM19653SI | |
| DATE | 11.05.2026 | |

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)
SAP No.6100016694

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

| | | | |
|--------------|------------|--------------|--|
| ON (Date) | 01.06.2026 | BY (Time) | |
|--------------|------------|--------------|--|

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: Complete Rehabilitation required for company owned vehicles CV-4783 and CU-2644 at Karachi Airport.

| S.No. | Description/Specifications | Location | Unit | Qty | Unit Price Rs. | Amount Rs. |
|-------|---|-------------------------------|------------|-----|-------------------|---------------|
| 11 | OEM recommended or equivalent Suspension Kit Set Complete Suspension Set Includes repairing of existing suspension set and installing new parts where needed. | Karachi (Aviation) | EA | 2 | | |
| 12 | Denting and Complete Shower | Karachi (Aviation) | | | | |
| 12.01 | Repairing,Denting&Painting Works The Job includes complete denting (where required), painting-Complete Body shower(Bhatti paint), interior cleaning, Installing new seat covers, carpet and matts and detailing of exterior body including rubbing, polishing and compounding of Toyota VIGO (4 doors) | | JOB | 1 | | |
| 12.02 | Repairing,Denting&Painting Works The Job includes complete denting (where required), painting-Complete Body shower(Bhatti paint), interior cleaning, Installing new seat covers, carpet and matts and detailing of exterior body including rubbing, polishing and compounding of Toyota Pickup (2 doors) | | JOB | 1 | | |
| 13 | Labour charges for mechanical work | Karachi (Aviation) | | | | |
| 13.01 | Engine Overhauling with commissioning Services including following for Toyota Vigo(4 Door) 1)Complete Engine Overhauling. 2)Dismantling of Engine from vehicle. 3)Assessment of Worn-out parts. 4)All required parts will be provided by the contractor. 5)Cleaning of all parts. 6)Assembling of engine. 7)Complete radiator service 8)Any other misc labour charges. | | JOB | 1 | | |
| 13.02 | Engine Overhauling with commissioning Services including following for Toyota Pickup(2 door) | | JOB | 1 | | |



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

| | | |
|--------|------------|---|
| 3 | OF | 3 |
| RFQ No | AM19653SI | |
| DATE | 11.05.2026 | |

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)
SAP No.6100016694

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

01.06.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. _____ PO/DD NO. _____

Title: Complete Rehabilitation required for company owned vehicles CV-4783 and CU-2644 at Karachi Airport.

| S.No. | Description/Specifications | Location | Unit | Qty | Unit Price Rs. | Amount Rs. |
|-------|--|----------|------|-----|-------------------|---------------|
| | 1)Complete Engine Overhauling. 2)Dismantling of Engine from vehicle. 3)Assessment of Worn-out parts. 4)All required parts will be provided by the contractor. 5)Cleaning of all parts. 6)Assembling of engine. 7)Complete radiator service 8)Any other misc labour charges. TERMS AND CONDITIONS: 1)All taxes are included in PR. 2)12 months of service warranty with parts/Labor charges must be given by vendor. 3)Approval/ Acceptance of overhauled engine/Cabin work subject to inspection of PSO KAP M-<>-R staff. 4)After completing the jobs, payment will be made against actual work done. 5) Worn out parts should be documented and handed over to PSO Karachi Aviation station representative. 6)All parts used must be brand new and equivalent to OEM recommendation. 7)Vendor should complete all the rehabilitation work within 40 days after issuance of PO. | | | | | |