



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

1	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
1	<b><u>Annual Cleaning and Maintenance- KHI PSO House</u></b> <b><u>DIY</u></b>					
1.01	<b><u>Annual Contract for Cleaning Services</u></b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "Cleaning and Painting Works at New Vision Retail Outlets (NVROs)" containing the scope of work in components A and B.  Please note that, break-up of the quoted price in the above-mentioned "Bill of Quantities" is mandatory.  (Here AU=EA and refers to NVROs)  For specification/scope of work/installation procedure of Fire extinguisher repair works including hose pipes, pressure gauge, valve, nozzle and trolley wheels, refer to the Annexure-05.		<b>AU</b>	1,800		
1.02	<b><u>Supply and Installation of Blue Bar</u></b> Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT  Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material.  Warranty 5 Years  Material Description: 1. Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing. 2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi ,stiffness (Rockwell M80-100) and optical clarity.		<b>ET</b>	2,000		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

2	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
1.03	<p>3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</p> <p>4. Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high tramittance.</p> <p>5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.</p> <p>JOB = RFT</p> <p><b>LED Tube Lights</b></p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rod&lt;(&gt;,&lt;)&gt; 4 feet at NVROs.</p> <p>Job includes:</p> <ul style="list-style-type: none"> <li>- Removal of existing tube rods from the fixture.</li> <li>- Installation of new LED rods in the fixture.</li> <li>- Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</li> <li>- Body: Plastic&lt;(&gt;,&lt;)&gt; Length: 4-feet&lt;(&gt;,&lt;)&gt; Diode: LED Body&lt;(&gt;,&lt;)&gt; thickness: 1200mm or above&lt;(&gt;,&lt;)&gt; Intensity: 1600 lumens or above&lt;(&gt;,&lt;)&gt; Power Rating: 10.5W-16W max.&lt;(&gt;,&lt;)&gt; Color: 5000K-6000K (White)&lt;(&gt;,&lt;)&gt; Color Rendering Index: 70 or above&lt;(&gt;,&lt;)&gt; Life Span: 15000 Hours or greater&lt;(&gt;,&lt;)&gt; Lux Level: Minimum of 2000 Lux (avg)&lt;(&gt;,&lt;)&gt; Operating Temp (degree): -10C to 60C</li> </ul>		EA	2,000		
1.04	<p><b>FIRE EXTINGUISHER 50 KG DCP</b></p> <p>Fire Extinguisher Re-Filling 50Kg.</p>		EA	200		
1.05	<p><b>FIRE EXTINGUISHER 6 KG DCP</b></p> <p>Fire Extinguisher Re-Filling 6Kg DCP.</p>		EA	1,500		
1.06	<p><b>Miscellaneous</b></p> <p>Fire Extinguisher Re-Filling 3Kg CO2.</p>		EA	180		
1.07	<p><b>Miscellaneous</b></p>		EA	100		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

3	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
1.08	S<(>&<)>I of Hose Pipe for 50Kg Trolley. <b>Miscellaneous</b>		<b>EA</b>	350		
1.09	S<(>&<)>I of Hose Pipe for 6Kg and 3 Kg. <b>Miscellaneous</b>		<b>EA</b>	350		
1.10	S<(>&<)>I of Pressure Gauge. <b>Miscellaneous</b>		<b>EA</b>	350		
1.11	S<(>&<)>I of Pressure Valve. <b>Miscellaneous</b>		<b>EA</b>	350		
1.12	S<(>&<)>I of Nozzle for Extinguishers. <b>Miscellaneous</b>		<b>EA</b>	150		
2	<b>Annual Cleaning and Maintenance- HYD PSO House DIY</b>					
2.01	<b>Annual Contract for Cleaning Services</b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "Cleaning and Painting Works at New Vision Retail Outlets (NVROs)" containing the scope of work in components A and B.  Please note that, break-up of the quoted price in the above-mentioned "Bill of Quantities" is mandatory.  (Here AU=EA and refers to NVROs)  For specification/scope of work/installation procedure of Fire extinguisher repair works including hose pipes, pressure gauge, valve, nozzle and trolley wheels, refer to the Annexure-05.		<b>AU</b>	1,300		
2.02	<b>Supply and Installation of Blue Bar</b>		<b>ET</b>	1,600		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

4	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
2.03	<p>Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT</p> <p>Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material.</p> <p>Warranty 5 Years</p> <p>Material Description:</p> <ol style="list-style-type: none"> <li>1. Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing.</li> <li>2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi ,stiffness (Rockwell M80-100) and optical clarity.</li> <li>3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</li> <li>4. Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high tramittance.</li> <li>5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.</li> </ol> <p>JOB = RFT</p> <p><b>LED Tube Lights</b></p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rod, 4 feet at NVROs.</p> <p>Job includes:</p> <ul style="list-style-type: none"> <li>- Removal of existing tube rods from the fixture.</li> <li>- Installation of new LED rods in the fixture.</li> </ul>		EA	1,600		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

5	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
	- Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand. - Body: Plastic, Length: 4-feet, Diode: LED Body, thickness: 1200mm or above, Intensity: 1600 lumens or above, Power Rating: 10.5W-16W max., Color: 5000K-6000K (White), Color Rendering Index: 70 or above, Life Span: 15000 Hours or greater, Lux Level: Minimum of 2000 Lux (avg), Operating Temp (degree): -10C to 60C					
2.04	<b><u>FIRE EXTINGUISHER 50 KG DCP</u></b> Fire Extinguisher Re-Filling 50Kg.		<b>EA</b>	200		
2.05	<b><u>FIRE EXTINGUISHER 6 KG DCP</u></b> Fire Extinguisher Re-Filling 6Kg DCP.		<b>EA</b>	1,500		
2.06	<b><u>Miscellaneous</u></b> Fire Extinguisher Re-Filling 3Kg CO2.		<b>EA</b>	200		
2.07	<b><u>Miscellaneous</u></b> S&I of Hose Pipe for 50Kg Trolley.		<b>EA</b>	50		
2.08	<b><u>Miscellaneous</u></b> S&I of Hose Pipe for 6Kg and 3 Kg.		<b>EA</b>	50		
2.09	<b><u>Miscellaneous</u></b> S&I of Pressure Gauge.		<b>EA</b>	65		
2.10	<b><u>Miscellaneous</u></b> S&I of Presuure Valve.		<b>EA</b>	65		
2.11	<b><u>Miscellaneous</u></b> S&I of Nozzle for Extinguishers.		<b>EA</b>	65		
2.12	<b><u>Miscellaneous</u></b> S&I of Trolley Wheel.		<b>EA</b>	65		
3	<b><u>Annual Cleaning and Maintenance- SUK PSO House</u></b> <b><u>DIY</u></b>					
3.01	<b><u>Annual Contract for Cleaning Services</u></b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "Cleaning and Painting Works at New Vision Retail Outlets (NVROs)" containing the scope of work in components A and B.  Please note that, break-up of the quoted price in the above-mentioned		<b>AU</b>	1,200		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

6	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
3.02	<p>"Bill of Quantities" is mandatory.</p> <p>(Here AU=EA and refers to NVROs)</p> <p>For specification/scope of work/installation procedure of Fire extinguisher repair works including hose pipes, pressure gauge, valve, nozzle and trolley wheels, refer to the Annexure-05.</p> <p><b>Supply and Installation of Blue Bar</b></p> <p>Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT</p> <p>Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material.</p> <p>Warranty 5 Years</p> <p>Material Description:</p> <ol style="list-style-type: none"> <li>Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing.</li> <li>Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi ,stiffness (Rockwell M80-100) and optical clarity.</li> <li>Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</li> <li>Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high tramittance.</li> <li>Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.</li> </ol>		ET	1,600		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

7	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ **PO/DD NO.** \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
3.03	JOB = RFT <b>LED Tube Lights</b> Supply, Installation, Testing and Commissioning of LED Tube Rod, 4 feet at NVROs. Job includes: - Removal of existing tube rods from the fixture. - Installation of new LED rods in the fixture. - Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand. - Body: Plastic, Length: 4-feet, Diode: LED Body, thickness: 1200mm or above, Intensity: 1600 lumens or above, Power Rating: 10.5W-16W max., Color: 5000K-6000K (White), Color Rendering Index: 70 or above, Life Span: 15000 Hours or greater, Lux Level: Minimum of 2000 Lux (avg), Operating Temp (degree): -10C to 60C		EA	1,600		
3.04	<b>FIRE EXTINGUISHER 50 KG DCP</b> Fire Extinguisher Re-Filling 50Kg.		EA	200		
3.05	<b>FIRE EXTINGUISHER 6 KG DCP</b> Fire Extinguisher Re-Filling 6Kg DCP.		EA	1,500		
3.06	<b>Miscellaneous</b> Fire Extinguisher Re-Filling 3Kg CO2.		EA	180		
3.07	<b>Miscellaneous</b> S&I of Hose Pipe for 50Kg Trolley.		EA	50		
3.08	<b>Miscellaneous</b> S&I of Hose Pipe for 6Kg and 3 Kg.		EA	50		
3.09	<b>Miscellaneous</b> S&I of Pressure Gauge.		EA	65		
3.10	<b>Miscellaneous</b> S&I of Pressure Valve.		EA	65		
3.11	<b>Miscellaneous</b> S&I of Nozzle for Extinguishers.		EA	65		
3.12	<b>Miscellaneous</b> S&I of Trolley Wheel.		EA	65		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

8	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
4	<b><u>Annual Cleaning and Maintenance- QTA PSO House</u></b> <b><u>DIY</u></b>					
4.01	<b><u>Annual Contract for Cleaning Services</u></b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "Cleaning and Painting Works at New Vision Retail Outlets (NVROs)" containing the scope of work in components A and B.  Please note that, break-up of the quoted price in the above-mentioned "Bill of Quantities" is mandatory.  (Here AU=EA and refers to NVROs)  For specification/scope of work/installation procedure of Fire extinguisher repair works including hose pipes, pressure gauge, valve, nozzle and trolley wheels, refer to the Annexure-05.		<b>AU</b>	300		
4.02	<b><u>Supply and Installation of Blue Bar</u></b> Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT  Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material.  Warranty 5 Years  Material Description: 1. Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing. 2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi ,stiffness (Rockwell M80-100) and optical clarity.		<b>ET</b>	500		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

9	OF	*
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON (Date)	16.04.2026	BY (Time)	
--------------	------------	--------------	--

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
4.03	<p>3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</p> <p>4. Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high tramittance.</p> <p>5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.</p> <p>JOB = RFT</p> <p><b>LED Tube Lights</b></p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rod, 4 feet at NVROs.</p> <p>Job includes:</p> <ul style="list-style-type: none"> <li>- Removal of existing tube rods from the fixture.</li> <li>- Installation of new LED rods in the fixture.</li> <li>- Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</li> <li>- Body: Plastic, Length: 4-feet, Diode: LED Body, thickness: 1200mm or above, Intensity: 1600 lumens or above, Power Rating: 10.5W-16W max., Color: 5000K-6000K (White), Color Rendering Index: 70 or above, Life Span: 15000 Hours or greater, Lux Level: Minimum of 2000 Lux (avg), Operating Temp (degree): -10C to 60C</li> </ul>		EA	400		
4.04	<b>FIRE EXTINGUISHER 50 KG DCP</b> Fire Extinguisher Re-Filling 50Kg.		EA	52		
4.05	<b>FIRE EXTINGUISHER 6 KG DCP</b> Fire Extinguisher Re-Filling 6Kg DCP.		EA	350		
4.06	<b>Miscellaneous</b> Fire Extinguisher Re-Filling 3Kg CO2.		EA	52		
4.07	<b>Miscellaneous</b> S&I of Hose Pipe for 50Kg Trolley.		EA	25		
4.08	<b>Miscellaneous</b> S&I of Hose Pipe for 6Kg and 3 Kg.		EA	50		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

10	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
4.09	<b>Miscellaneous</b> S&I of Pressure Gauge.		EA	15		
4.10	<b>Miscellaneous</b> S&I of Presuure Valve.		EA	15		
4.11	<b>Miscellaneous</b> S&I of Nozzle for Extinguishers.		EA	15		
4.12	<b>Miscellaneous</b> S&I of Trolley Wheel.		EA	15		
5	<b>Annual Cleaning and Maintenance- LHR PSO House DIY</b>					
5.01	<b>Annual Contract for Cleaning Services</b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B.  (Here AU=EA and refers to NVROs)		AU	2,090		
5.02	<b>FIRE EXTINGUISHER 50 KG DCP</b> Refilling of DCP 50kg Fire trolley  Refilling of Fire cylinders/trolley in the division as per Annex-C attached.		EA	475		
5.03	<b>FIRE EXTINGUISHER 6 KG DCP</b> Refilling of DCP 6kg Fire cylinder  Refilling of Fire cylinders in the division as per Annex-C attached.		EA	2,600		
5.04	<b>Refilling of Fire Extinguishers</b> Re-Filling of 3Kg CO2 Cylinder  Refilling of Fire cylinder/trolley as per Annex-C Attached.		EA	560		
5.05	<b>Providing &amp; Replac. of Hose Pipe for FFs</b>		EA	65		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

11	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON (Date)	16.04.2026	BY (Time)	
--------------	------------	--------------	--

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
5.06	S&I of Hose Pipe for 50Kg Trolley <b>Providing &amp; Replac. of Hose Pipe for FFs</b>		EA	195		
5.07	S&I of Hose Pipe for 6Kg and 3 Kg <b>Pressure Gauge</b>		EA	170		
5.08	S&I of Pressure Gauge <b>Miscellaneous</b>		EA	170		
5.09	S&I of Presuure Valve <b>Installation of Nozzle</b>		EA	170		
5.10	S&I of Nozzle for Extinguishers <b>INSTALLATION OF FIRE EXTINGUISHER</b>		EA	33		
5.11	S<(>&<)>l of Trolley Wheel as per required specs. <b>Placement/Installation of LED Tube Rods</b> REPLACEMENT OF LED RODs  Supply, Installation, Testing and Commissioning of LED Tube Rods in Company Signage i.e. Name Plate, Spreaders, Blue bars, Wall logo Canopy logo, Tyreshop, Fiber glass tower (logo and plates) and other company signage/fittings.  Job includes: Removal of existing tube rods from the fixture. Installation of new LED rods in the fixture. Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.  LED rod specifications: Body: Plastic Length: 4-feet for all signage except canopy logo (2-feet for canopy logo). Diode: LED Body thickness: 1200mm or above Intensity: 1600 lumens or above Power Rating: 10.5W-16W max. Color: 5000K-6000K (White)		EA	2,400		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

12	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
	<p>Color Rendering Index: 70 or above Life Span: 15000 Hours or greater Lux Level: Minimum of 2000 Lux (avg) Operating Temp (degree): -10C to 60C</p> <p>Terms &amp; Conditions &amp; related documents attached: 1.,,Annex-A: Special Terms &amp; Conditions of Work Order for Cleaning of NVROs. 2.,,Annex-B: Cleaning Scope (BOQ. 3. Annex-C: Refilling of Fire Extinguishers/trolley. 4.,,Annex-D: List of Chemicals Material tools and equipment. 5.,,Annex-E: SLA for Cleaning, Fire Refilling and LED rod replacement. 6. Annex-F: Checklist-Cleaning items inventory on Cleaning Vehicle. 7.,,Annex-G: Checklist-Cleaning items inventory at Warehouse/workshop. 8. Annex-H: HSE documents 9. Annex-I: Technical Evaluation Criteria (Cleaning Demo). 10. Annex-J: PUR-03</p>					
5.12	<p><b>Supply and Installation of Blue Bar</b> Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT Supply and Installation of Acrylic / Perspex light bar in 5mm thick Acrylic / Perspex sheet. The light bar is to be molded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material. Warranty 5 Years Material Description: 1. Acrylic sheet with a thickness of 5 mm is to be used, molded in the required shape, size and colour as per the drawing. 2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi-&lt;&gt; ,&lt;&gt; stiffness (Rockwell M80-100) and optical clarity.</p>		<b>ET</b>	2,650		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

13	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
6	<p>3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</p> <p>4. Acrylic should not be easily affected by moisture (water absorption (0.2% - 0.4%) and must have a high strength to weight ratio and high remittance.</p> <p>5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.</p> <p>JOB = RFT</p> <p><b><u>Annual Cleaning and Maintenance- BWP PSO House</u></b> <b><u>DIY</u></b></p>					
6.01	<p><b><u>Annual Contract for Cleaning Services</u></b></p> <p>It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B.</p> <p>(Here AU=EA and refers to NVROs)</p>		<b>AU</b>	1,214		
6.02	<p><b><u>FIRE EXTINGUISHER 50 KG DCP</u></b></p> <p>Refilling of DCP 50kg Fire Trolley</p> <p>Refilling of Fire cylinders/ Trolley in the division as per Annex-C attached.</p>		<b>EA</b>	180		
6.03	<p><b><u>FIRE EXTINGUISHER 6 KG DCP</u></b></p> <p>Refilling of DCP 6kg Fire cylinder</p> <p>Refilling of Fire cylinders in the division as per Annex-C attached.</p>		<b>EA</b>	1,380		
6.04	<p><b><u>Refilling of Fire Extinguishers</u></b></p> <p>Re-Filling of 3Kg CO2 Cylinder</p>		<b>EA</b>	60		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

14	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
	Refilling of Fire cylinder/trolley as per Annex-C Attached.					
6.05	<b>Providing &amp; Replac. of Hose Pipe for FFs</b> S&I of Hose Pipe for 50Kg Trolley		EA	60		
6.06	<b>Providing &amp; Replac. of Hose Pipe for FFs</b> S&I of Hose Pipe for 6Kg and 3 Kg		EA	60		
6.07	<b>Pressure Gauge</b> S&I of Pressure Gauge		EA	105		
6.08	<b>Miscellaneous</b> S&I of Presuure Valve		EA	120		
6.09	<b>Installation of Nozzle</b> S&I of Nozzle for Extinguishers		EA	75		
6.10	<b>INSTALLATION OF FIRE EXTINGUISHER</b> S&I of Trolley Wheel		EA	30		
	Terms & Conditions & related documents attached: 1.,,Appendix "A" Special Terms & Conditions of Work Order for Cleaning of NVROs. 2.,,Appendix "B": PUR-03 3.,,Appendix "C": List of Chemicals 4.,,Appendix "D": SLA 5.,,Bill of Quantity Appendix "E" 6.,,Job Hazard Analysis (JHA 09 Nos) 7.,,HSE documents					
6.11	<b>Placement/Installation of LED Tube Rods</b> REPLACEMENT OF LED RODs  Supply, Installation, Testing and Commissioning of LED Tube Rods in Company Signage i.e. Name Plate, Spreaders, Blue bars, Wall logo Canopy logo, Tyreshop, Fiber glass tower (logo and plates) and other company signage/fittings.  Job includes: Removal of existing tube rods from the fixture. Installation of new LED rods in the fixture.		EA	2,200		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

15	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
	<p>Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</p> <p>LED rod specifications:            Body: Plastic            Length: 4-feet for all signage except canopy logo (2-feet for canopy logo).            Diode: LED            Body thickness: 1200mm or above            Intensity: 1600 lumens or above            Power Rating: 10.5W-16W max.            Color: 5000K-6000K (White)            Color Rendering Index: 70 or above            Life Span: 15000 Hours or greater            Lux Level: Minimum of 2000 Lux (avg)            Operating Temp (degree): -10C to 60C</p> <p>Terms &amp; Conditions &amp; related documents attached:            1.,,Annex-A: Special Terms &amp; Conditions of Work Order for Cleaning of NVROs.            2.,,Annex-B: Cleaning Scope BOQ.            3. Annex-C: Refilling of Fire Extinguishers/trolley.            4.,,Annex-D: List of Chemicals Material tools and equipment.            5.,,Annex-E: SLA for Cleaning, Fire Refilling and LED rod replacement.            6. Annex-F: Checklist-Cleaning items inventory on Cleaning Vehicle.            7.,,Annex-G: Checklist-Cleaning items inventory at Warehouse/workshop.            8. Annex-H: HSE documents            9. Annex-I: Technical Evaluation Criteria (Cleaning Demo).            10. Annex-J: PUR-03</p>					
6.12	<b>Supply and Installation of Blue Bar</b>		<b>ET</b>			
	Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT				1,886.800	



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

16	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
7	Supply and Installation of Acrylic / Perspex light bar in 5mm thick Acrylic / Perspex sheet. The light bar is to be molded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material. Warranty 5 Years Material Description: 1. Acrylic sheet with a thickness of 5 mm is to be used, molded in the required shape, size and colour as per the drawing. 2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi , stiffness (Rockwell M80-100) and optical clarity. 3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform. 4. Acrylic should not be easily affected by moisture (water absorption (0.2% - 0.4%) and must have a high strength to weight ratio and high remittance. 5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent. JOB = RFT					
7.01	<b><u>Annual Cleaning and Maintenance- FSD PSO House</u></b> <b><u>DIY</u></b> <b><u>Annual Contract for Cleaning Services</u></b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B.  (Here AU=EA and refers to NVROs)		<b>AU</b>	1,386		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

17	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
7.02	<b><u>FIRE EXTINGUISHER 50 KG DCP</u></b> Refilling of DCP 50kg Fire Trolley  Refilling of Fire cylinders/ Trolley in the division as per Annex-C attached.		<b>EA</b>	250		
7.03	<b><u>FIRE EXTINGUISHER 6 KG DCP</u></b> Refilling of DCP 6kg Fire cylinder  Refilling of Fire cylinders in the division as per Annex-C attached.		<b>EA</b>	1,430		
7.04	<b><u>Refilling of Fire Extinguishers</u></b> Re-Filling of 3Kg CO2 Cylinder  Refilling of Fire cylinder/trolley as per Annex-C Attached.		<b>EA</b>	343		
7.05	<b><u>Providing &amp; Replac. of Hose Pipe for FEs</u></b> S&I of Hose Pipe for 50Kg Trolley		<b>EA</b>	16		
7.06	<b><u>Providing &amp; Replac. of Hose Pipe for FEs</u></b> S&I of Hose Pipe for 6Kg and 3 Kg		<b>EA</b>	47		
7.07	<b><u>Pressure Gauge</u></b> S&I of Pressure Gauge		<b>EA</b>	78		
7.08	<b><u>Miscellaneous</u></b> S&I of Presuure Valve		<b>EA</b>	94		
7.09	<b><u>Installation of Nozzle</u></b> S&I of Nozzle for Extinguishers		<b>EA</b>	31		
7.10	<b><u>INSTALLATION OF FIRE EXTINGUISHER</u></b> S&I of Trolley Wheel		<b>EA</b>	16		
<p>Terms &amp; Conditions &amp; related documents attached:</p> <p>1.,,Appendix "A" Special Terms &amp; Conditions of Work Order for Cleaning of NVROs.</p> <p>2.,,Appendix "B": PUR-03</p> <p>3.,,Appendix "C": List of Chemicals</p>						



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

18	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
7.11	<p>4.,,Appendix "D": SLA 5.,,Bill of Quantity Appendix "E" 6.,,Job Hazard Analysis (JHA 09 Nos) 7.,,HSE documents</p> <p><b>Placement/Installation of LED Tube Rods</b> REPLACEMENT OF LED RODs</p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rods in Company Signage i.e. Name Plate, Spreaders, Blue bars, Wall logo Canopy logo, Tyreshop, Fiber glass tower (logo and plates) and other company signage/fitings.</p> <p>Job includes: Removal of existing tube rods from the fixture. Installation of new LED rods in the fixture. Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</p> <p>LED rod specifications: Body: Plastic Length: 4-feet for all signage except canopy logo (2-feet for canopy logo). Diode: LED Body thickness: 1200mm or above Intensity: 1600 lumens or above Power Rating: 10.5W-16W max. Color: 5000K-6000K (White) Color Rendering Index: 70 or above Life Span: 15000 Hours or greater Lux Level: Minimum of 2000 Lux (avg) Operating Temp (degree): -10C to 60C</p> <p>Terms &amp; Conditions &amp; related documents attached: 1.,,Annex-A: Special Terms &amp; Conditions of Work Order for Cleaning of NVROs.</p>		EA	2,000		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

19	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
2.,	Annex-B: Cleaning Scope (BOQ).					
3.	Annex-C: Refilling of Fire Extinguishers/trolley.					
4.,	Annex-D: List of Chemicals Material tools and equipment.					
5.,	Annex-E: SLA for Cleaning, Fire Refilling and LED rod replacement.					
6.	Annex-F: Checklist-Cleaning items inventory on Cleaning Vehicle.					
7.,	Annex-G: Checklist-Cleaning items inventory at Warehouse/workshop.					
8.	Annex-H: HSE documents					
9.	Annex-I: Technical Evaluation Criteria (Cleaning Demo).					
10.	Annex-J: PUR-03					
7.12	<p><b>Supply and Installation of Blue Bar</b></p> <p>Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT</p> <p>Supply and Installation of Acrylic / Perspex light bar in 5mm thick Acrylic / Perspex sheet. The light bar is to be molded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material.</p> <p>Warranty 5 Years</p> <p>Material Description:</p> <ol style="list-style-type: none"> <li>Acrylic sheet with a thickness of 5 mm is to be used, molded in the required shape, size and colour as per the drawing.</li> <li>Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi , stiffness (Rockwell M80-100) and optical clarity.</li> <li>Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</li> <li>Acrylic should not be easily affected by moisture (water absorption (0.2% - 0.4%) and must have a high strength to weight ratio and high remittance.</li> <li>Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500</li> </ol>		<b>FT</b>	2,491		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

20	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %**  
Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
8	series/Equivalent. JOB = RFT <b>Annual Cleaning and Maintenance- GRW PSO House DIY</b>					
8.01	<b>Annual Contract for Cleaning Services</b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B.  (Here AU=EA and refers to NVROs)		<b>AU</b>	1,254		
8.02	<b>FIRE EXTINGUISHER 50 KG DCP</b> Refilling of DCP 50kg Fire Trolley  Refilling of Fire cylinders/ Trolley in the division as per Annex-C attached.		<b>EA</b>	200		
8.03	<b>FIRE EXTINGUISHER 6 KG DCP</b> Refilling of DCP 6kg Fire cylinder  Refilling of Fire cylinders in the division as per Annex-C attached.		<b>EA</b>	900		
8.04	<b>Refilling of Fire Extinguishers</b> Re-Filling of 3Kg CO2 Cylinder  Refilling of Fire cylinder/trolley as per Annex-C Attached.		<b>EA</b>	220		
8.05	<b>Providing &amp; Replac. of Hose Pipe for FFs</b> S&I of Hose Pipe for 50Kg Trolley		<b>EA</b>	173		
8.06	<b>Providing &amp; Replac. of Hose Pipe for FFs</b>		<b>EA</b>	504		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

21	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON (Date)	16.04.2026	BY (Time)	
--------------	------------	--------------	--

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
8.07	S&I of Hose Pipe for 6Kg and 3 Kg <b>Pressure Gauge</b>		<b>EA</b>	432		
8.08	S&I of Pressure Gauge <b>Miscellaneous</b>		<b>EA</b>	173		
8.09	S&I of Presuure Valve <b>Installation of Nozzle</b>		<b>EA</b>	173		
8.10	S&I of Nozzle for Extinguishers <b>INSTALLATION OF FIRE EXTINGUISHER</b>		<b>EA</b>	144		
	S&I of Trolley Wheel					
	Terms & Conditions & related documents attached: 1.,,Appendix "A" Special Terms & Conditions of Work Order for Cleaning of NVROs. 2.,,Appendix "B": PUR-03 3.,,Appendix "C": List of Chemicals 4.,,Appendix "D": SLA 5.,,Bill of Quantity Appendix "E" 6.,,Job Hazard Analysis (JHA 09 Nos) 7.,,HSE documents					
8.11	<b>Placement/Installation of LED Tube Rods</b> REPLACEMENT OF LED RODs  Supply, Installation, Testing and Commissioning of LED Tube Rods in Company Signage i.e. Name Plate, Spreaders, Blue bars, Wall logo Canopy logo, Tyreshop, Fiber glass tower (logo and plates) and other company signage/fittings.  Job includes: Removal of existing tube rods from the fixture. Installation of new LED rods in the fixture. Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.  LED rod specifications: Body: Plastic		<b>EA</b>	2,000		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

22	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
8.12	<p>Length: 4-feet for all signage except canopy logo (2-feet for canopy logo). Diode: LED Body thickness: 1200mm or above Intensity: 1600 lumens or above Power Rating: 10.5W-16W max. Color: 5000K-6000K (White) Color Rendering Index: 70 or above Life Span: 15000 Hours or greater Lux Level: Minimum of 2000 Lux (avg) Operating Temp (degree): -10C to 60C</p> <p>Terms &amp; Conditions &amp; related documents attached: 1.,Annex-A: Special Terms &amp; Conditions of Work Order for Cleaning of NVROs. 2.,Annex-B: Cleaning Scope (BOQ). 3. Annex-C: Refilling of Fire Extinguishers/trolley. 4.,Annex-D: List of Chemicals Material tools and equipment. 5.,Annex-E: SLA for Cleaning, Fire Refilling and LED rod replacement. 6. Annex-F: Checklist-Cleaning items inventory on Cleaning Vehicle. 7.,Annex-G: Checklist-Cleaning items inventory at Warehouse/workshop. 8. Annex-H: HSE documents 9. Annex-I: Technical Evaluation Criteria (Cleaning Demo). 10. Annex-J: PUR-03</p> <p><b>Supply and Installation of Blue Bar</b></p> <p>Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT Supply and Installation of Acrylic / Perspex light bar in 5mm thick Acrylic / Perspex sheet. The light bar is to be molded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved</p>		<b>ET</b>			1,823.200



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

23	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
9	<p>converters / applicator. Joint of adjacent two acrylic bars to be covered with same material. Warranty 5 Years Material Description:</p> <ol style="list-style-type: none"> <li>Acrylic sheet with a thickness of 5 mm is to be used, molded in the required shape, size and colour as per the drawing.</li> <li>Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi , stiffness (Rockwell M80-100) and optical clarity.</li> <li>Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</li> <li>Acrylic should not be easily affected by moisture (water absorption (0.2% - 0.4%) and must have a high strength to weight ratio and high remittance.</li> <li>Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent. JOB = RFT</li> </ol> <p><b><u>Annual Cleaning and Maintenance- MLT PSO House</u></b> <b><u>DIY</u></b></p>					
9.01	<p><b><u>Annual Contract for Cleaning Services</u></b></p> <p>It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B.</p> <p>(Here AU=EA and refers to NVROs)</p>		<b>AU</b>	1,452		
9.02	<p><b><u>FIRE EXTINGUISHER 50 KG DCP</u></b></p> <p>Refilling of DCP 50kg Fire Trolley</p> <p>Refilling of Fire cylinders/ Trolley in the division as per Annex-C attached.</p>		<b>EA</b>	220		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

24	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
9.03	<b><u>FIRE EXTINGUISHER 6 KG DCP</u></b> Refilling of DCP 6kg Fire cylinder  Refilling of Fire cylinders in the division as per Annex-C attached.		<b>EA</b>	1,025		
9.04	<b><u>Refilling of Fire Extinguishers</u></b> Re-Filling of 3Kg CO2 Cylinder  Refilling of Fire cylinder/trolley as per Annex-C Attached.		<b>EA</b>	204		
9.05	<b><u>Providing &amp; Replac. of Hose Pipe for FFs</u></b> S&I of Hose Pipe for 50Kg Trolley		<b>EA</b>	62.400		
9.06	<b><u>Providing &amp; Replac. of Hose Pipe for FFs</u></b> S&I of Hose Pipe for 6Kg and 3 Kg		<b>EA</b>	62.400		
9.07	<b><u>Pressure Gauge</u></b> S&I of Pressure Gauge		<b>EA</b>	204		
9.08	<b><u>Miscellaneous</u></b> S&I of Presuure Valve		<b>EA</b>	192		
9.09	<b><u>Installation of Nozzle</u></b> S&I of Nozzle for Extinguishers		<b>EA</b>	180		
9.10	<b><u>INSTALLATION OF FIRE EXTINGUISHER</u></b> S&I of Trolley Wheel		<b>EA</b>	60		
Terms & Conditions & related documents attached: 1.,,Appendix "A" Special Terms & Conditions of Work Order for Cleaning of NVROs. 2.,,Appendix "B": PUR-03 3.,,Appendix "C": List of Chemicals 4.,,Appendix "D": SLA 5.,,Bill of Quantity Appendix "E" 6.,,Job Hazard Analysis (JHA 09 Nos) 7.,,HSE documents						



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

25	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
9.11	<p><b>Placement/Installation of LED Tube Rods</b></p> <p>REPLACEMENT OF LED RODS</p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rods in Company Signage i.e. Name Plate, Spreaders, Blue bars, Wall logo Canopy logo, Tyreshop, Fiber glass tower (logo and plates) and other company signage/fittings.</p> <p>Job includes:</p> <p>Removal of existing tube rods from the fixture.</p> <p>Installation of new LED rods in the fixture.</p> <p>Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</p> <p>LED rod specifications:</p> <p>Body: Plastic</p> <p>Length: 4-feet for all signage except canopy logo (2-feet for canopy logo).</p> <p>Diode: LED</p> <p>Body thickness: 1200mm or above</p> <p>Intensity: 1600 lumens or above</p> <p>Power Rating: 10.5W-16W max.</p> <p>Color: 5000K-6000K (White)</p> <p>Color Rendering Index: 70 or above</p> <p>Life Span: 15000 Hours or greater</p> <p>Lux Level: Minimum of 2000 Lux (avg)</p> <p>Operating Temp (degree): -10C to 60C</p> <p>Terms &amp; Conditions &amp; related documents attached:</p> <p>1.,,Annex-A: Special Terms &amp; Conditions of Work Order for Cleaning of NVROs.</p> <p>2.,,Annex-B: Cleaning Scope (BOQ).</p> <p>3. Annex-C: Refilling of Fire Extinguishers/trolley.</p> <p>4.,,Annex-D: List of Chemicals Material tools and equipment.</p> <p>5.,,Annex-E: SLA for Cleaning, Fire Refilling and LED rod</p>		EA	2,200		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

26	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
9.12	<p>replacement.</p> <p>6. Annex-F: Checklist-Cleaning items inventory on Cleaning Vehicle.</p> <p>7.,,Annex-G: Checklist-Cleaning items inventory at Warehouse/workshop.</p> <p>8. Annex-H: HSE documents</p> <p>9. Annex-I: Technical Evaluation Criteria (Cleaning Demo).</p> <p>10. Annex-J: PUR-03</p> <p><b>Supply and Installation of Blue Bar</b></p> <p>Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT</p> <p>Supply and Installation of Acrylic / Perspex light bar in 5mm thick Acrylic / Perspex sheet. The light bar is to be molded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material.</p> <p>Warranty 5 Years</p> <p>Material Description:</p> <p>1. Acrylic sheet with a thickness of 5 mm is to be used, molded in the required shape, size and colour as per the drawing.</p> <p>2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi , stiffness (Rockwell M80-100) and optical clarity.</p> <p>3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</p> <p>4. Acrylic should not be easily affected by moisture (water absorption (0.2% - 0.4%) and must have a high strength to weight ratio and high remittance.</p> <p>5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.</p> <p>JOB = RFT</p>		ET	2,024.600		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

27	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %**  
Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
10	<b><u>Annual Cleaning and Maintenance- SWL PSO House</u></b> <b><u>DIY</u></b>					
10.01	<b><u>Annual Contract for Cleaning Services</u></b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B.  (Here AU=EA and refers to NVROs)		<b>AU</b>	1,294		
10.02	<b><u>FIRE EXTINGUISHER 50 KG DCP</u></b> Refilling of DCP 50kg Fire Trolley  Refilling of Fire cylinders/ Trolley in the division as per Annex-C attached.		<b>EA</b>	180		
10.03	<b><u>FIRE EXTINGUISHER 6 KG DCP</u></b> Refilling of DCP 6kg Fire cylinder  Refilling of Fire cylinders in the division as per Annex-C attached.		<b>EA</b>	1,047		
10.04	<b><u>Refilling of Fire Extinguishers</u></b> Re-Filling of 3Kg CO2 Cylinder  Refilling of Fire cylinder/trolley as per Annex-C Attached.		<b>EA</b>	180		
10.05	<b><u>Providing &amp; Replac. of Hose Pipe for FFs</u></b> S&I of Hose Pipe for 50Kg Trolley		<b>EA</b>	58		
10.06	<b><u>Providing &amp; Replac. of Hose Pipe for FFs</u></b> S&I of Hose Pipe for 6Kg and 3 Kg		<b>EA</b>	58		
10.07	<b><u>Pressure Gauge</u></b> S&I of Pressure Gauge		<b>EA</b>	35		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

28	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
10.08	<b>Miscellaneous</b> S&I of Presuure Valve		<b>EA</b>	58		
10.09	<b>Installation of Nozzle</b> S&I of Nozzle for Extinguishers		<b>EA</b>	35		
10.10	<b>INSTALLATION OF FIRE EXTINGUISHER</b> S&I of Trolley Wheel		<b>EA</b>	15		
	Terms & Conditions & related documents attached: 1.,,Appendix "A" Special Terms & Conditions of Work Order for Cleaning of NVROs. 2.,,Appendix "B": PUR-03 3.,,Appendix "C": List of Chemicals 4.,,Appendix "D": SLA 5.,,Bill of Quantity Appendix "E" 6.,,Job Hazard Analysis (JHA 09 Nos) 7.,,HSE documents					
10.11	<b>Placement/Installation of LED Tube Rods</b> REPLACEMENT OF LED RODS		<b>EA</b>	1,800		
	Supply, Installation, Testing and Commissioning of LED Tube Rods in Company Signage i.e. Name Plate, Spreaders, Blue bars, Wall logo Canopy logo, Tyreshop, Fiber glass tower (logo and plates) and other company signage/fittings.  Job includes: Removal of existing tube rods from the fixture. Installation of new LED rods in the fixture. Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.  LED rod specifications: Body: Plastic Length: 4-feet for all signage except canopy logo (2-feet for canopy logo). Diode: LED					



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

29	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON (Date)	16.04.2026	BY (Time)	
--------------	------------	--------------	--

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
10.12	<p>Body thickness: 1200mm or above Intensity: 1600 lumens or above Power Rating: 10.5W-16W max. Color: 5000K-6000K (White) Color Rendering Index: 70 or above Life Span: 15000 Hours or greater Lux Level: Minimum of 2000 Lux (avg) Operating Temp (degree): -10C to 60C</p> <p><b>Supply and Installation of Blue Bar</b></p> <p>Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5th May 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material. Warranty 5 Years Material Description: 1. Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing. 2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi , stiffness (Rockwell M80-100) and optical clarity. 3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform. 4. Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high remittance. 5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent. JOB = RFT</p>		ET	1,802		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

30	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
11	<p>Terms &amp; Conditions &amp; related documents attached:</p> <ol style="list-style-type: none"> <li>Annex-A: Special Terms &amp; Conditions of Work Order for Cleaning of NVROs.</li> <li>Annex-B: Cleaning Scope (BOQ).</li> <li>Annex-C: Refilling of Fire Extinguishers/trolley.</li> <li>Annex-D: List of Chemicals Material tools and equipment.</li> <li>Annex-E: SLA for Cleaning, Fire Refilling, LED rod and Blue bars replacement.</li> <li>Annex-F: Checklist-Cleaning items inventory on Cleaning at Workshop /Warehouse or Vehicle.</li> <li>Annex-G: HSE documents</li> <li>Annex-H: Technical Evaluation Criteria (Cleaning Demo).</li> <li>Annex-I: General Terms and Condition</li> </ol> <p><b>Annual Cleaning and Maintenance-15B PSO House</b> <b>DIY</b></p>					
11.01	<p><b>Annual Contract for Cleaning Services</b></p> <p>It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B.</p> <p>(Here AU=EA and refers to NVROs)</p> <p>For specification/scope of work/installation procedure of Fire extinguisher repair works including hose pipes, pressure gauge, valve, nozzle and trolley wheels, refer to the Annexure-05</p>		<b>AU</b>	1,500		
11.02	<p><b>FIRE EXTINGUISHER 50 KG DCP</b></p> <p>Fire Extinguisher Re-Filling 50Kg</p>		<b>EA</b>	275		
11.03	<p><b>FIRE EXTINGUISHER 6 KG DCP</b></p> <p>Fire Extinguisher Re-Filling 6Kg DCP</p>		<b>EA</b>	1,500		
11.04	<p><b>Refilling of Fire Extinguishers</b></p>		<b>EA</b>	275		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

31	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
11.05	Fire Extinguisher Re-Filling 3Kg CO2 <b>Providing &amp; Replac. of Hose Pipe for FFs</b>		EA	100		
11.06	S&I of Hose Pipe for 50Kg Trolley <b>Providing &amp; Replac. of Hose Pipe for FFs</b>		EA	500		
11.07	S&I of Hose Pipe for 6Kg and 3 Kg <b>Pressure Gauge</b>		EA	250		
11.08	S&I of Pressure Gauge <b>Miscellaneous</b>		EA	250		
11.09	S&I of Presuure Valve <b>Installation of Nozzle</b>		EA	250		
11.10	S&I of Nozzle for Extinguishers <b>INSTALLATION OF FIRE EXTINGUISHER</b>		EA	250		
11.11	S&I of Trolley Wheel <b>Supply and Installation of Blue Bar</b> Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5thMay 2017)and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approvedconverters/ applicator. Joint of adjacent two acrylic bars to be covered with samematerial. Warranty 5 Years Material Description: 1. Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing. 2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi ,stiffness (Rockwell M80-100) and optical clarity. 3. Acrylic sheet should have to be easily		ET	3,000		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

32	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
11.12	<p>fabricated; bonds well with adhesive sand solvents and should have a property of thermoform. 4. Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high transmittance. 5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.</p> <p><b>LED Tube Lights</b></p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rod, 4 feet at NVROs.</p> <p>Job includes:</p> <ul style="list-style-type: none"> <li>- Removal of existing tube rods from the fixture.</li> <li>- Installation of new LED rods in the fixture.</li> <li>- Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</li> <li>- Body: Plastic, Length: 4-feet, Diode: LED Body, thickness: 1200mm or above, Intensity: 1600 lumens or above, Power Rating: 10.5W-16W max., Color: 5000K-6000K (White), Color Rendering Index: 70 or above, Life Span: 15000 Hours or greater, Lux Level: Minimum of 2000 Lux (avg), Operating Temp (degree): -10C to 60C</li> </ul> <p>Terms &amp; Conditions &amp; related documents attached:</p> <ol style="list-style-type: none"> <li>1.,,Appendix "A": CHKLST-Cleaning Items Inventory-Vehicle</li> <li>2.,,Appendix "B": CHKLST-Cleaning Items Inventory -Workshop and Site</li> <li>3.,,Appendix "C": List of Chemicals</li> <li>4.,,Appendix "D": SLA</li> <li>5.,,Appendix 05 Fire Extinguishers</li> <li>6.,,Job Hazard Analysis (JHA 09 Nos)</li> <li>7.,,HSE documents</li> <li>8.,,Special Terms &amp; Conditions of Work Order for Cleaning of NVROs.</li> <li>9.,,General Terms &amp; Conditions of Work Order for Cleaning of NVROs.</li> <li>10.,,Appendix 06 Blue Bar drawing</li> <li>11.,, Cleaning BOQ</li> <li>12.,, TEC -Cleaning contract</li> <li>13.,, TEC -Demo Cleaning contract</li> </ol>		EA	3,200		
12	<b>Annual Cleaning and Maintenance-JHL</b>	PSO House				
	<b>DIY</b>					



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

33	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON (Date)	16.04.2026	BY (Time)	
--------------	------------	--------------	--

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
12.01	<b>Annual Contract for Cleaning Services</b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B. (Here AU=EA and refers to NVROs)  For specification/scope of work/installation procedure of Fire extinguisher repair works including hose pipes, pressure gauge, valve, nozzle and trolley wheels, refer to the Annexure-05		<b>AU</b>	620		
12.02	<b>FIRE EXTINGUISHER 50 KG DCP</b> Fire Extinguisher Re-Filling 50Kg		<b>EA</b>	117		
12.03	<b>FIRE EXTINGUISHER 6 KG DCP</b> Fire Extinguisher Re-Filling 6Kg DCP		<b>EA</b>	754		
12.04	<b>Refilling of Fire Extinguishers</b> Fire Extinguisher Re-Filling 3Kg CO2		<b>EA</b>	117		
12.05	<b>Providing &amp; Replac. of Hose Pipe for FFs</b> S&I of Hose Pipe for 50Kg Trolley		<b>EA</b>	13		
12.06	<b>Providing &amp; Replac. of Hose Pipe for FFs</b> S&I of Hose Pipe for 6Kg and 3 Kg		<b>EA</b>	156		
12.07	<b>Pressure Gauge</b> S&I of Pressure Gauge		<b>EA</b>	52		
12.08	<b>Miscellaneous</b> S&I of Presuure Valve		<b>EA</b>	39		
12.09	<b>Installation of Nozzle</b> S&I of Nozzle for Extinguishers		<b>EA</b>	5		
12.10	<b>INSTALLATION OF FIRE EXTINGUISHER</b> S&I of Trolley Wheel		<b>EA</b>	7		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

34	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
12.11	<p><b>Supply and Installation of Blue Bar</b></p> <p>Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT</p> <p>Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5thMay 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approved converters / applicator. Joint of adjacent two acrylic bars to be covered with same material.</p> <p>Warranty 5 Years</p> <p>Material Description:</p> <ol style="list-style-type: none"> <li>1. Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing.</li> <li>2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi ,stiffness (Rockwell M80-100) and optical clarity.</li> <li>3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</li> <li>4. Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high tramittance.</li> <li>5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent. JOB = RFT</li> </ol>		ET	1,500		
12.12	<p><b>LED Tube Lights</b></p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rod, 4 feet at NVROs.</p> <p>Job includes:</p> <ul style="list-style-type: none"> <li>- Removal of existing tube rods from the fixture.</li> </ul>		EA	1,800		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

35	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
13	<p>- Installation of new LED rods in the fixture.</p> <p>- Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</p> <p>- Body: Plastic, Length: 4-feet, Diode: LED Body, thickness: 1200mm or above, Intensity: 1600 lumens or above, Power Rating: 10.5W-16W max., Color: 5000K-6000K (White), Color Rendering Index: 70 or above, Life Span: 15000 Hours or greater, Lux Level: Minimum of 2000 Lux (avg), Operating Temp (degree): -10C to 60C</p> <p>Terms &amp; Conditions &amp; related documents attached:</p> <p>1.,,Appendix "A": CHKLST-Cleaning Items Inventory-Vehicle</p> <p>2.,,Appendix "B": CHKLST-Cleaning Items Inventory -Workshop and Site</p> <p>3.,,Appendix "C": List of Chemicals</p> <p>4.,,Appendix "D": SLA</p> <p>5.,,Appendix 05 Fire Extinguishers</p> <p>6.,,Job Hazard Analysis (JHA 09 Nos)</p> <p>7.,,HSE documents</p> <p>8.,,Special Terms &amp; Conditions of Work Order for Cleaning of NVROs.</p> <p>9.,,General Terms &amp; Conditions of Work Order for Cleaning of NVROs.</p> <p>10.,, Appendix 06 Blue Bar drawing</p> <p>11.,, Cleaning BOQ</p> <p>12.,, TEC -Cleaning contract</p> <p>13.,, TEC -Demo Cleaning contract</p> <p><b><u>Annual Cleaning and Maintenance-PSW PSO House</u></b> <b><u>DTV</u></b></p>					
13.01	<p><b><u>Annual Contract for Cleaning Services</u></b></p> <p>It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B.</p> <p>(Here AU=EA and refers to NVROs)</p> <p>For specification/scope of work/installation procedure of Fire extinguisher repair works including hose pipes, pressure gauge, valve, nozzle and trolley wheels, refer to the Annexure-05</p>		<b>AU</b>	970		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

36	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
13.02	<b><u>FIRE EXTINGUISHER 50 KG DCP</u></b> Fire Extinguisher Re-Filling 50Kg		EA	230		
13.03	<b><u>FIRE EXTINGUISHER 6 KG DCP</u></b> Fire Extinguisher Re-Filling 6Kg DCP		EA	950		
13.04	<b><u>Refilling of Fire Extinguishers</u></b> Fire Extinguisher Re-Filling 3Kg CO2		EA	200		
13.05	<b><u>Providing &amp; Replac. of Hose Pipe for FEs</u></b> S&I of Hose Pipe for 50Kg Trolley		EA	150		
13.06	<b><u>Providing &amp; Replac. of Hose Pipe for FEs</u></b> S&I of Hose Pipe for 6Kg and 3 Kg		EA	400		
13.07	<b><u>Pressure Gauge</u></b> S&I of Pressure Gauge		EA	300		
13.08	<b><u>Miscellaneous</u></b> S&I of Presuure Valve		EA	300		
13.09	<b><u>Installation of Nozzle</u></b> S&I of Trolley Wheel		EA	300		
13.10	<b><u>INSTALLATION OF FIRE EXTINGUISHER</u></b> S&I of Trolley Wheel		EA	150		
13.11	<b><u>Supply and Installation of Blue Bar</u></b> Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT  Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5thMay 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approvedconverters		ET	2,000		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

37	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
13.12	<p>/ applicator. Joint of adjacent two acrylic bars to be covered with same material.</p> <p>Warranty 5 Years</p> <p>Material Description:</p> <ol style="list-style-type: none"> <li>Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing.</li> <li>Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi ,stiffness (Rockwell M80-100) and optical clarity.</li> <li>Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform.</li> <li>Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high tramittance.</li> <li>Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.</li> </ol> <p>JOB = RFT</p> <p><b>LED Tube Lights</b></p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rod, 4 feet at NVROs.</p> <p>Job includes:</p> <ul style="list-style-type: none"> <li>- Removal of existing tube rods from the fixture.</li> <li>- Installation of new LED rods in the fixture.</li> <li>- Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</li> <li>- Body: Plastic, Length: 4-feet, Diode: LED Body, thickness: 1200mm or above, Intensity: 1600 lumens or above, Power Rating: 10.5W-16W max., Color: 5000K-6000K (White), Color Rendering Index: 70 or above, Life Span: 15000 Hours or greater, Lux Level: Minimum of 2000 Lux (avg), Operating Temp (degree): -10C to 60C</li> </ul> <p>Terms &amp; Conditions &amp; related documents attached:</p>		EA	1,500		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

38	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
14	1.,,Appendix "A": CHKLST-Cleaning Items Inventory-Vehicle 2.,,Appendix "B": CHKLST-Cleaning Items Inventory -Workshop and Site 3.,,Appendix "C": List of Chemicals 4.,,Appendix "D": SLA 5.,,Appendix 05 Fire Extinguishers 6.,,Job Hazard Analysis (JHA 09 Nos) 7.,,HSE documents 8.,,Special Terms & Conditions of Work Order for Cleaning of NVROs. 9.,,General Terms & Conditions of Work Order for Cleaning of NVROs. 10.,,Appendix 06 Blue Bar drawing 11.,, Cleaning BOQ 12.,, TEC -Cleaning contract 13.,, TEC -Demo Cleaning contract <b>Annual Cleaning and Maintenance-DIK PSO House</b> <b>DIY</b>					
14.01	<b>Annual Contract for Cleaning Services</b> It is the Total (Rs.) per Retail Outlet/Visit of the attached "Bill of Quantities" having the title "REPAIR AND MAINTENANCE WORKS AT NEW VISION RETAIL OUTLETS (NVROs) containing the scope of work in components A and B. (Here AU=EA and refers to NVROs)  For specification/scope of work/installation procedure of Fire extinguisher repair works including hose pipes, pressure gauge, valve, nozzle and trolley wheels, refer to the Annexure-05		<b>AU</b>	840		
14.02	<b>FIRE EXTINGUISHER 50 KG DCP</b> Fire Extinguisher Re-Filling 50Kg		<b>EA</b>	150		
14.03	<b>FIRE EXTINGUISHER 6 KG DCP</b> Fire Extinguisher Re-Filling 6Kg DCP		<b>EA</b>	780		
14.04	<b>Refilling of Fire Extinguishers</b> Fire Extinguisher Re-Filling 3Kg CO2		<b>EA</b>	150		
14.05	<b>Providing &amp; Replac. of Hose Pipe for FEs</b> S&I of Hose Pipe for 50Kg Trolley		<b>EA</b>	75		
14.06	<b>Providing &amp; Replac. of Hose Pipe for FEs</b> S&I of Hose Pipe for 6Kg and 3 Kg		<b>EA</b>	100		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

39	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor  
PAKISTAN

### QUOTATION REQUIRED

ON  
(Date)

16.04.2026

BY  
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
14.07	<b>Pressure Gauge</b> S&I of Pressure Gauge		<b>EA</b>	100		
14.08	<b>Miscellaneous</b> S&I of Presuure Valve		<b>EA</b>	100		
14.09	<b>Installation of Nozzle</b> S&I of Nozzle for Extinguishers		<b>EA</b>	100		
14.10	<b>INSTALLATION OF FIRE EXTINGUISHER</b> S&I of Trolley Wheel		<b>EA</b>	25		
14.11	<b>Supply and Installation of Blue Bar</b> Supply and Installation of new Blue Bar- 5mm on canopy fascia-- Per RFT  Supply and Installation of Acrylic / perspex light bar in 5mm thick Acrylic / perspex sheet. The light bar is to be moulded to required shape as per attached sketch( PSO Dwg No: S-006 Rev:5 dated 5thMay 2017) and fitted with 3M film i.e. 3M (3630 VT 1986) /Avery CC (5500-763 Blue)/Equivalent should be applied by a qualified and approvedconverters / applicator. Joint of adjacent two acrylic bars to be covered with same material.  Warranty 5 Years  Material Description: 1. Acrylic sheet with a thickness of 5 mm is to be used, moulded in the required shape, size and colour as per the drawing. 2. Acrylic should be thermoplastic with an outstanding strength (min: Compressive strength of 11 ksi and min: Tensile Strength of 560 psi ,stiffness (Rockwell M80-100) and optical clarity. 3. Acrylic sheet should have to be easily fabricated; bonds well with adhesive sand solvents and should have a property of thermoform. 4. Acrylic should not be easily affected by moisture (water absorption 0.2% - 0.4%) and must have a high strength to weight ratio and high tramittance. 5. Vinyl Pasting- Electronically cutting and Pasting with Translucent Blue (PSO Standard blue) Vinyl of 3M- 3630 series/Avery- 5500 series/Equivalent.		<b>ET</b>	2,000		



# Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan  
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

40	OF	40
RFQ No	RFA4855SZ	
DATE	28.03.2026	

## REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)  
SAP No.6100016265

Company PSO Dummy Vendor PAKISTAN	QUOTATION REQUIRED		
	ON (Date)	16.04.2026	BY (Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith **EARNEST MONEY %** Rs. \_\_\_\_\_ PO/DD NO. \_\_\_\_\_

**Title:** Services Required for Cleaning of Retail Outlets, Repair / Refilling of Fire Extinguishers and Replacement of LED rods and Blue Bars at NVROs across Pakistan

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
14.12	<p>JOB = RFT</p> <p><b>LED Tube Lights</b></p> <p>Supply, Installation, Testing and Commissioning of LED Tube Rod, 4 feet at NVROs.</p> <p>Job includes:</p> <ul style="list-style-type: none"> <li>- Removal of existing tube rods from the fixture.</li> <li>- Installation of new LED rods in the fixture. - Electrical Rewiring for the rod (if required) with 3/0.029 gauge wire of Pakistan cables or approved brand.</li> <li>- Body: Plastic, Length: 4-feet, Diode: LED Body, thickness: 1200mm or above, Intensity: 1600 lumens or above, Power Rating: 10.5W-16W max., Color: 5000K-6000K (White), Color Rendering Index: 70 or above, Life Span: 15000 Hours or greater, Lux Level: Minimum of 2000 Lux (avg), Operating Temp (degree): -10C to 60C</li> </ul> <p>Terms &amp; Conditions &amp; related documents attached:</p> <ol style="list-style-type: none"> <li>1.,,Appendix "A": CHKLST-Cleaning Items Inventory-Vehicle</li> <li>2.,,Appendix "B": CHKLST-Cleaning Items Inventory -Workshop and Site</li> <li>3.,,Appendix "C": List of Chemicals</li> <li>4.,,Appendix "D": SLA</li> <li>5.,,Appendix 05 Fire Extinguishers</li> <li>6.,,Job Hazard Analysis (JHA 09 Nos)</li> <li>7.,,HSE documents</li> <li>8.,,Special Terms &amp; Conditions of Work Order for Cleaning of NVROs.</li> <li>9.,,General Terms &amp; Conditions of Work Order for Cleaning of NVROs.</li> <li>10.,,Appendix 06 Blue Bar drawing 11.,, Cleaning BOQ</li> <li>12.,, TEC -Cleaning contract</li> <li>13.,, TEC -Demo Cleaning contract</li> </ol>		EA	1,500		