



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan

Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

1	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
1	<u>Refilling of Fire Extinguishers - KTA</u>	<u>Keamari Terminal</u>				
1.01	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg.		<u>KG</u>	2,000.000		
1.02	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs		<u>KG</u>	400.000		
1.03	<u>Refilling of Fire Extinguishers by Weigh</u> Repair of DCP FEs Valves. Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve leakage. Replacement of operating valve/handle/wheel (if required)		<u>KG</u>	15.000		
1.04	<u>Refilling of Fire Extinguishers by Weigh</u> Providing & replacement of valves (CO2) Providing and Replacement of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.		<u>KG</u>	10.000		
1.05	<u>Refilling of Fire Extinguishers by Weigh</u> Providing & replacement of valves (CO2) Providing and Replacement of operating valve for CO2 type fire extinguishers Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.		<u>KG</u>	5.000		
1.06	<u>Refilling of Fire Extinguishers by Weigh</u> Presssure Gauge fitted with DCP FEs Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher.		<u>KG</u>	15.000		
1.07	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	15.000		



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan

Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

2	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
1.08	DCP hose pipe replacement Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	6.000		
2	CO2 hose pipe replacement Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for CO2 type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. =====					
2.01	<u>Refilling of Fire Extinguishers - KTB</u>	<u>Keamari Terminal</u>				
2.01	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	2,000.000		
2.02	Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	600.000		
2.03	Refilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	15.000		
2.04	Repair of DCP F.Ext. Valve Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve leakage. Replacement of operating valve/handle/wheel (if required) <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	10.000		
2.05	Providing & replacement of valves (CO2) Providing and Replacement of operating valve for DCP type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	5.000		
	Providing & replacement of valves (CO2) Providing and Replacement of operating valve for CO2 type fire extinguishers Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.					



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

3	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
2.06	<u>Refilling of Fire Extinguishers by Weigh</u> Presssure Gauge fitted with DCP FEs Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher.		<u>KG</u>	15.000		
2.07	<u>Refilling of Fire Extinguishers by Weigh</u> DCP hose pipes replacement Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories.		<u>KG</u>	10.000		
2.08	<u>Refilling of Fire Extinguishers by Weigh</u> CO2 hose pipe replacement Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for CO2 type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. =====		<u>KG</u>	6.000		
3	<u>Refilling of Fire Extinguishers - KTC</u>	<u>Keamari Terminal</u>				
3.01	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg.		<u>KG</u>	1,500.000		
3.02	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs		<u>KG</u>	200.000		
3.03	<u>Refilling of Fire Extinguishers by Weigh</u> Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve leakage. Replacement of operating valve/handle/wheel (if required)		<u>KG</u>	10.000		
3.04	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and re-installation of new		<u>KG</u>	20.000		



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

4	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
3.05	valve, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of operating valve for CO2 type fire extinguishers Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.		<u>KG</u>	10.000		
3.06	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher.		<u>KG</u>	30.000		
3.07	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories.		<u>KG</u>	20.000		
3.08	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for CO2 type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. =====		<u>KG</u>	10.000		
4	<u>Refilling of Fire Extinguishers - ZOT</u>	<u>Keamari Terminal</u>				
4.01	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg.		<u>KG</u>	3,000.000		
4.02	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs		<u>KG</u>	800.000		
4.03	<u>Refilling of Fire Extinguishers by Weigh</u> Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve leakage. Replacement of operating valve/handle/wheel (if required)		<u>KG</u>	20.000		
4.04	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of operating valve for DCP type fire		<u>KG</u>	20.000		



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

5	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
4.05	extinguishers Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	10.000		
4.06	Providing and Replacement of operating valve for CO2 type fire extinguishers Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	25.000		
4.07	Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	10.000		
4.08	Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	10.000		
5	=====					
	<u>Refilling of Fire Extinguishers - SKP</u>	<u>Keamari Terminal</u>				
5.01	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg.		<u>KG</u>	1,200.000		
5.02	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs		<u>KG</u>	100.000		
5.03	<u>Refilling of Fire Extinguishers by Weigh</u> Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve leakage. Replacement of operating valve/handle/wheel (if required)		<u>KG</u>	10.000		



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan

Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

6	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
5.04	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of operating valve for DCP type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.		<u>KG</u>	6.000		
5.05	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of operating valve for CO2 type fire extinguishers Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.		<u>KG</u>	5.000		
5.06	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher.		<u>KG</u>	15.000		
5.07	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories.		<u>KG</u>	5.000		
5.08	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for CO2 type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. =====		<u>KG</u>	5.000		
6	<u>Refilling of Fire Extinguishers - DLP</u>	<u>Keamari Terminal</u>				
6.01	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg.		<u>KG</u>	1,000.000		
6.02	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs		<u>KG</u>	100.000		
6.03	<u>Refilling of Fire Extinguishers by Weigh</u> Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve		<u>KG</u>	10.000		



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan

Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

7	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
6.04	leakage. Replacement of operating valve/handle/wheel (if required) <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	6.000		
	Providing and Replacement of operating valve for DCP type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.					
6.05	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	5.000		
	Providing and Replacement of operating valve for CO2 type fire extinguishers Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.					
6.06	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	15.000		
	Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher.					
6.07	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	5.000		
	Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories.					
6.08	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	5.000		
	Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for CO2 type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. =====					
7	<u>Refilling of Fire Extinguishers - SNGI</u>	<u>Keamari Terminal</u>				
7.01	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	400.000		
	Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg.					
7.02	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	50.000		
	Refilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs					
7.03	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	1.000		
	Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve					



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan

Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

8	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
7.04	leakage. Replacement of operating valve/handle/wheel (if required) <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	3.000		
7.05	Providing and Replacement of operating valve for DCP type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	2.000		
7.06	Providing and Replacement of operating valve for CO2 type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	5.000		
7.07	Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	2.000		
7.08	Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	2.000		
8	Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for CO2 type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. Annual Services for Refilling of Fire Extinguishers is required at Sanghi depot on as and when required basis during the mentioned period. Job include transportation of Fire Extinguishers from location within 2-3 days after informing <(>&<)> bring back duly filled-in within 3-4 working days. Each F.Ext must possess a sticker mentioning Filling Co's name, capacity, type of Fire Extinguisher, date of filling <(>&<)> Expiry. Job include cleaning and pressure testing of Fire Extinguisher upto its safe working pressure. The contractor will ensure use of class A,B,C Dry Chemical Powder. <u>Refilling of Fire Extinguishers - QTA</u>	<u>Quetta (Depot)</u>				
8.01	<u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	400.000		



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

9	OF	*
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)


25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
8.02	Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	50.000		
8.03	RRefilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	1.000		
8.04	Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve leakage. Replacement of operating valve/handle/wheel (if required) <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	3.000		
8.05	Providing and Replacement of operating valve for DCP type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	2.000		
8.06	Providing and Replacement of operating valve for CO2 type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	5.000		
8.07	Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	2.000		
8.08	Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories. <u>Refilling of Fire Extinguishers by Weigh</u>		<u>KG</u>	2.000		
9	<u>Refilling of Fire Extinguishers -</u> <u>KHZ</u>	<u>Khuzdar</u> <u>(Depot)</u>				
9.01	<u>Refilling of Fire Extinguishers by Weigh</u> Refilling of DCP Type Fire Extinguishers of different capacities ranging from 6 kg to 100 kg.		<u>KG</u>	400.000		



SAP No 6100017781

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
9.02	<u>Refilling of Fire Extinguishers by Weigh</u> RRefilling of CO2 Type Fire Extinguishers of different capacities ranging from 3-50 kgs		<u>KG</u>	50.000		
9.03	<u>Refilling of Fire Extinguishers by Weigh</u> Repairing of operating valve for DCP type fire extinguishers Scope includes dismantling of faulty valve and rectification of valve leakage. Replacement of operating valve/handle/wheel (if required)		<u>KG</u>	1.000		
9.04	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of operating valve for DCP type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.		<u>KG</u>	3.000		
9.05	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of operating valve for CO2 type fire extinguishers. Scope includes dismantling of faulty valve and re-installation of new valve, compatible with the fire extinguisher.		<u>KG</u>	2.000		
9.06	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of faulty Pressure gauge for DCP type fire extinguishers Scope includes dismantling of faulty gauge and re-installation of new gauge, compatible with the fire extinguisher.		<u>KG</u>	5.000		
9.07	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for DCP type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories.		<u>KG</u>	2.000		
9.08	<u>Refilling of Fire Extinguishers by Weigh</u> Providing and Replacement of damaged hose pipes along with discharge nozzle and spreader for CO2 type Fire Extinguisher. Scope includes dismantling and refitting of hose pipe with all allied accessories.		<u>KG</u>	2.000		
	SCOPE OF WORK FOR REPAIR/REFILLING/PAINTING FIRE EXTINGUISHERS: =====					
	a) The contractor will collect all empty Fire Extinguishers in batches from the Locations with loading/unloading and return back after refilling will be responsibility of contractor. A*The contractor should collect the Fire extinguishers from the location and return these after refilling/recharging within					



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan

Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

11	OF	13
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
	3-4 working days. Otherwise, Penalty of Rs. 500 per day / per cylinder will be imposed. b) The contractor will return the Fire Extinguishers after re-filling/services with in 10 working days. c) The contractor will give warranty of at least 1 year for the refilled cylinders/extinguishers. If the Extinguisher /trolley fails to operate at any time with in its period the contractor shall be liable to refill it free of cost. d) The contractor will provide at least 50 % of total collected quantity as back up at the site. e) Scope of work also includes: * Cleaning, clearing of vessel from DCP or pressure of CO2 at site. * Pressure testing of the vessel up to safe working pressure. * Refilling/recharging of DCP/CO2 up to rated capacity and standard pressure. * Refilling of CO2 Cylinders as per standard pressure with opening and re-installation with DCP Trolleys. * Renew validity tags on all Fire Extinguishers after refilling. f) The dry chemical powder for fire extinguisher classes A, B and C is to be used/provided by the contractor. g) Transportation Charges for collecting, loading, unloading of Fire Extinguishers one batch from Location and shifting these back after refilling, will be responsibility of contractor. h) As per NFPA 10: Hydrostatic testing report of fire extinguishers should also be submitted at location. *Fire extinguishers operate under high internal pressures (approximately 15 bar for DCP and 55 bar for CO# extinguishers). General TERMS and CONDITIONS: ===== 1) Rates are inclusive of all kind of Govt. taxes, etc. 2) The contractor has to follows PSO's HSE Policy strictly. 3) Contractor should maintain housekeeping of the worksite.					



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan
Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

12	OF	13
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
	4) All labor, tools material, instruments and others to be provided by contractor. 5) If the Contractor fails to complete the job within stipulated time <(>,<)> PSO will be entitled to deduct .1% of WO/SO value per day as liquidated damages for the period (maximum of 10% of the value of WO/SO. 7) The work will only be accepted after 100 % completion of job and approval by the DI/IM/Eng. 8) Payment will be made as per actual work done. 9) Quality is the prime concern of PSO, no compromise shall be made in this regard.Only 1st class approved quality material, workmanship and supervision will be utilized by the contractor which is strictly confirm to the WO/SO specification. 10)Part payment will be allowed. 11) Contractor will be responsible for any damages during Transportation /Loading /Unloading process. 12)The contractor should give warranty of at least 1 year for the refilled cylinders/extinguishers. If the Extinguisher/trolley fails to operate at any time with in its period the contractor shall be liable to refill it free of cost. 13) The contractor should provide at least 50 % of total collected quantity as back up at the terminal 14) Contractor must follow PSO HSE Policy and will be responsible for security of Fire Extinguishers outside PSO premises. 15) Quantities may increase or decrease as per requirement and payment will be made as per actual work done by the contractor. 16) Contract may be renewed for next year 02 years based on contractor's performance and mutual agreement by both the parties with the same rates/terms and conditions. 17) The contract may be extendable up to 3 months on same terms and conditions with out any consent of the Contractor.					



Pakistan State Oil Company Limited

PSO House, Khayaban-e-Iqbal, Clifton, Karachi-75600, Pakistan

Telephone (021) 9203866-85 Fax (021) 9203796

PAGE

13	OF	13
RFQ No	OP-A4917NZ	
DATE	07.08.2026	

REQUEST FOR QUOTATION

(THIS IS PRICE ENQUIRY-NOT AN ORDER)

SAP No.6100017781

Company PSO Dummy Vendor
PAKISTAN

QUOTATION REQUIRED

ON
(Date)

25.08.2026

BY
(Time)

Please quote your best price for all items of following specifications. Please read the instructions attached herewith Rs. _____ EARNEST MONEY %
PO/DD NO. _____

Title: ANNUAL CONTRACT FOR REFILLING/REPAIRING OF FIRE EXTINGUISHERS AT SOUTH ZONE LOCATIONS
W.E.F 01.01.2027 to 31.12.2027

S.No.	Description/Specifications	Location	Unit	Qty	Unit Price Rs.	Amount Rs.
	Special Terms and conditions: #1. The contractor shall submit a batch wise service completion report certifying that all services have been carried out in accordance with the Work Order specifications and applicable standards. 2. PSO reserves the right to inspect and verify any fire extinguisher before acceptance. Any extinguisher found non-compliant shall be rejected and re-serviced/replaced by the contractor at no additional cost. 3. All reports, test certificates, warranty documents, and service tags required under the Work Order shall be submitted along with each completed batch. 4. The Engineer/Inspection Officer may witness any stage of inspection, hydrostatic testing, refilling, or functional testing at the contractor's facility. The contractor shall provide access and necessary assistance. 5. Acceptance of the work shall be subject to satisfactory verification of the submitted records and physical inspection by the Engineer/Inspection Officer. 6. Payment shall be released only after successful inspection and acceptance of the completed work and submission of all required documentation. 7. If any extinguisher is found deficient during inspection or within the warranty period due to poor workmanship or non-compliance with the specifications, the contractor shall rectify the deficiency within 48 hours at no additional cost. 8. PSO reserves the right to conduct random audits of serviced fire extinguishers during the contract period. Any repeated non-compliance may result in rejection of the batch, recovery of associated costs, or termination of the contract as per the applicable terms.					